

**LEACHATE COLLECTION WELLS  
OM&M MONITORING AND BAILING DATA SHEET  
WASTE DISPOSAL, INC. SUPERFUND SITE**

DATE: October 4, 2007

TECHNICIAN NAME: ROCKA, P.J.

TECHNICIAN SIGNATURE Paul J. Rocka

WELL ID	BOTTOM OF WELL AFTER CONSTRUCT-ED [TOTAL DEPTH] (ft)	MEASURED BOTTOM OF WELL [TOTAL DEPTH] (ft)	GAUGING TIME		DEPTH TO LIQUID (ft)						HEIGHT OF LIQUID COLUMN (ft)		VOLUME OF LIQUID REMOVED (gallons)	COMMENTS
			Start	Finish	Start			Finish			Start	Finish		
					1 <sup>st</sup> Rdg.	2nd Rdg.	3 <sup>rd</sup> Rdg.	1 <sup>st</sup> Rdg.	2nd Rdg.	3 <sup>rd</sup> Rdg.				
LC-1	22.25	22.24	0013	0026	19.27	19.27	19.27	21.98	21.98	21.98				
LC-2	21.90	21.90	0035	0054	13.05	13.05	13.05	21.63	21.63	21.63				
LC-3	22.20													
LC-4	21.90	21.90	0101	0123	12.88	12.88	12.88	21.70	21.70	21.70				

W:\InterimOpMain+Mon\LeachateCollectionWells\WorkPlan+FieldForms\February2007\Feb107LC-WellsM&B(YF1).doc



**LEACHATE COLLECTION WELLS  
OM&M INSPECTION SHEET  
WASTE DISPOSAL, INC. SUPERFUND SITE**

INSPECTOR'S NAME	INSPECTOR'S SIGNATURE	INSPECTION TIME	INSPECTION DATE
ROCKA ID. J.	Paul S. Rocka	0000	October 4, 2007

ITEM OF POTENTIAL CONCERN	CONDITIONS OBSERVED				COMMENTS	CHECK (✓) BELOW WHEN COMPLETED
	WELL ID LC-1	WELL ID LC-2	WELL ID LC-3	WELL ID LC-4		
Wellhead (well box, cover, gasket, concrete)	OK	OK	—	OK		✓✓✓
Well Casing and Cap/Plug	OK	OK	—	OK		✓✓✓
Liquid Present in Well Box	NO	NO	—	NO		✓✓✓
Other:						
Other:						
Other:						

W:\InterimOpMain+Mon\LeachateCollectionWells\WorkPlan+FieldForms\February2007\Feb507LC-Wellsinspection(YF).doc

# DAILY FIELD REPORT

JOB NAME: WASTE DISPOSAL, INC. (WDI)	PROJECT NUMBER: 125154/001400	DATE: 10/4/2007
LOCATION: Santa Fe Springs, California	WEATHER: FAIR	DAY: Thursday
OM&M CONTRACTOR: TRC	FOREMAN:	
FIELD TECHNICIAN: ROCKFAP-J.	INSPECTION/TESTING OF: LEACHATE MONITORING/CONTROL SYSTEM	
SUMMARY OF OPERATIONS/WORK PERFORMED::		
ARRIVED @ SITE, OPEN GATE, DROVE AROUND. TO CHECK		
OUT EVERYTHING. PLACE DOLLS OUT ON TAILGATE.. #55G. DRUM.		
DROVE UP TO WELL.. OPEN IT, PLACE NETS AROUND		
WELL # AROUND CASING TO PREVENT SPILLS. THEN GAUGE		
3X TOTAL DEPTH W/ CLEANING OFF SOUNDER EVERY TIME &		
DEPTH TO PRODUCT.. THEN BEGAN BAILING OUT PRODUCT		
AFTER SEVERAL GAUGE WELL 3X MORE W/ EVERY TIME		
CLEANING OFF SOUNDER. AFTER RECORD READINGS		
CLEAN WELL CASING & CLOSED UP LID. REPEATED ALL STEPS		
FOR EVERY WELL.. ONCE COMPLETED DROVE TO WHERE		
DRUMS WERE LOCATED & PLACED DRUM BACK.. THEN DRAINED		
OUT KNOCKOUT POT.. ONCE DONE DROVE AROUND SITE ONCE		
MORE. THEN DROVE BACK TO SFS TO FAX PAPERWORK..		
& Fill out this FINAL REPORT..		
		
		 <small>Customer-Focused Solutions</small>

Note: Specific System Data and Observations are Included on "OM&M Inspection Sheets" and "OM&M Monitoring and Bailing Data Sheets"

**DAILY FIELD REPORT**  
WASTE DISPOSAL, INC  
SANTA FE SPRINGS, CALIFORNIA

**TRC**

FIGURE J.1